

From: The Imaging Source Product Management
Date: April 22nd, 2024
Subject: End-Of-Life for The Imaging Source cameras with onsemi MT9P006 sensors.

Reasons for discontinuation:

As a result of the sensor discontinuation of MT9P006 by the supplier **onsemi**, some **TIS cameras** are being retired according to the schedule specified below.
The recommended replacements, providing similar functionality, are also indicated in the table below.

Camera Series: 2U Series (USB 2.0)		
Model	Recommended Replacement	Last Time Buy Date
DFM 72BUC02-ML	DFM 32UR0521-ML	May 17 th , 2024
DFM 72BUC02-MLA	DFM 32UR0521-MLA	May 17 th , 2024
DFM 72BUC02-MLPB	DFM 32UR0521-MLPB	May 17 th , 2024
DFK 72AUC02	DFK 32AUR0521	May 17 th , 2024
DFK 72BUC02	DFK 32BUR0521	May 17 th , 2024

We hope that this notification allows you time to complete existing projects and shift future projects to one of our other and more advanced products.

Do not hesitate to contact our sales department if you have any questions or need additional information.

Any supply will be subject to TIS's capacity and resource constraints.
Obligations beyond the final ship date will be limited to warranty support only.
The supply of products will be subject to TIS's general terms and conditions of sale or any specific contractual terms agreed between the parties.
