

**From:** The Imaging Source's Product Management  
**Date:** January 8<sup>th</sup>, 2026  
**Subject:** End-Of-Life for The Imaging Source cameras with Sony IMX415 sensors.

**Reasons for discontinuation:**

As a result of the sensor discontinuation of IMX415 by the supplier Sony, some **TIS cameras** are being retired according to the schedule specified below.  
 The recommended replacements, providing similar functionality, are also indicated in the table below.

<b>Camera Series: 36S (MIPI CSI-2), 36A (MIPI CSI-2), 36C (FPD-Link III)</b>		
<b>Model</b>	<b>Recommended Replacement</b>	<b>Last Time Buy Date</b>
<b>DMM 36SX415-ML</b>	<b>DMM 36SR2020-ML</b>	March 8 <sup>th</sup> , 2026
<b>DFM 36SX415-ML</b>	<b>DFM 36SR2020-ML</b>	March 8 <sup>th</sup> , 2026
<b>DMM 36AX415-ML</b>	<b>DMM 36SR2020-ML</b>	March 8 <sup>th</sup> , 2026
<b>DFM 36AX415-ML</b>	<b>DFM 36SR2020-ML</b>	March 8 <sup>th</sup> , 2026
<b>DMM 36CX415-ML</b>	n/a	March 8 <sup>th</sup> , 2026
<b>DFM 36CX415-ML</b>	n/a	March 8 <sup>th</sup> , 2026
<b>DMK 36CX415-I67</b>	<b>AcM 36DR2020-I67 (GMSL2)</b>	March 8 <sup>th</sup> , 2026
<b>DFK 36CX415-I67</b>	<b>AcC 36DR2020-I67 (GMSL2)</b>	March 8 <sup>th</sup> , 2026

We hope that this notification allows you time to complete existing projects and shift future projects to one of our other and more advanced products.

Do not hesitate to contact our sales department if you have any questions or need additional information.

---

Any supply will be subject to TIS's capacity and resource constraints.

Obligations beyond the final ship date will be limited to warranty support only.

The supply of products will be subject to TIS's general terms and conditions of sale or any specific contractual terms agreed between the parties.

---